

Sanitized Copy Approved for Release 2009/11/16 : CIA-RDP89B00569R000800100018-7 TMS

DATE 2040Z 18 DEC 63

SECRET

1	9
2	10
3	11
4	12
5	13
6	14
7	15
8	16

TO 25X1 RECTOR

FROM

ACTION:

INFO :

OPS 1-12

TOR: 2121Z 18 DEC 63

PRIORITY

IN 55087

25X1

TO PRIORITY

0157

25X1

3256/181100Z/342

25X1

1. 775, 37

2. 100 PERCENT

3. REMARKS: MANY SIGNALS NOTED ON ALL RECEIVERS. OPERATION NORMAL.

25X1

1. 701, 74,, 13, 11, 50, 16, 1005, 1002.

2. 100 PERCENT

3. REMARKS: SOME SIGNALS ON ALL BANDS. OPERATION NORMAL.

25X1

25 YEAR RE-REVIEW

1. 3

2. REMARKS: NO ACTIVITY OBSERVED.

25X1

1. 4, 4, 4, 4.

2. REMARKS: NO ACTIVITY OBSERVED.

SECRET

GROUP 1
Excluded from automatic
downgrading and
declassification

REPRODUCTION BY OTHER THAN THE ISSUING OFFICE IS PROHIBITED. Copy No.

Sanitized Copy Approved for Release 2009/11/16 : CIA-RDP89B00569R000800100018-7

25X1

S E C R E T

 1057 - IN 55087

PAGE TWO


 25X1

N/A

RADIO AND NAVAIDS

VOR NOT WORKING DURING MSN. ANALYSIS IN PROGRESS. WILL GIVE REPORT LATER. UNIT WORKED PERFECT DURING PREFLIGHT CHECK AT 0430 LOCAL TODAY. 618T WAS CYCLED TO WRONG FREQ ON GROUND BEFORE TAKEOFF. WAS RECYCLED AT 1106Z.

BIRDWATCHER

100 PERCENT. PILOT SAID BW WAS OK. ON TWO CHECK POINTS HEAVY QRM PREVENTED READOUT. SOME READOUTS WERE SHORTER THAN THE NORMAL  BELIEVE THIS DUE TO KEYING RELAY BECAUSE ALL GROUND PRE-FLIGHT TESTS WERE NORMAL.

END OF MSG

25X1